

ELECTRO INDUSTRIES - FIELD SERVICE BULLETIN

Bulletin Number 1106 Date 02-10-07

Product Name Electro-Boiler, Zone Controller

Affected Product Model Numbers: EB-ZTA and EB-ZEA

Serial # _____ through _____

ARL # _____ through _____

Production Date 2/2/07 through Present

FIELD INFORMATION

Issue

The priority timeout on standard zone controller is 1 hour. During some large domestic hot water applications, 1 hour is not long enough.

Solution

A revised software plug-in chip has been created to extend the 1 hour priority to 4 hours.

To activate this 4 hour priority, must request from factory chip version 3.32 (R-116).

Information Document

Request and review BC031.

Approval W Supala Date 5-15-07