

# ELECTRO INDUSTRIES - FIELD SERVICE BULLETIN

Bulletin Number 1080 Date July 8, 2003

Product Name Make-Up Air – Blower Inlet – Possible A/C Feedback with Interlocking Furnace Blower

Effected Product Model Numbers:

	<u>CSA</u>	<u>Production Date</u>
EM-WH0515J	0-331	5-22-03
EM-WH1025K	0-331	5-22-03

## FIELD INFORMATION

Reference installation manual EI903, page 3, bottom – INTERLOCK FURNACE BLOWER

Depending upon roomstat or roomstat sub-base characteristics, the hookup shown on the bottom of page 3 could present a feedback situation where this connection could also turn on the air conditioner from a feedback between G and Y.

The hookup shown below could prevent this feedback and probably presents a more reliable connection.

Note: The G wire from the roomstat does **not** go to the furnace fan center, it must be extended and connected to the blower inlet unit as shown below. The G on the furnace fan center must have only one wire.

<b>Blower Inlet (Photo B)</b>	<b>Furnace Fan Center</b>	<b>Roomstat</b>
NO	R	-
BL	G	-
NC	-	G

Installation manual updated 7-8-03.

Approval



Date

7-8-03